

HYTORC

TOOL MODEL:HY- .7MXT

PRESSURE/TORQUE CONVERSION CHART

| PRESSURE IN PSI | TORQUE IN | | | PRESSURE IN BAR |
|--------------------|-----------|-----|------|--------------------|
| | FT. LBS. | KGM | NM | |
| 1500 | 118 | 16 | 160 | 104 |
| 1600 | 126 | 17 | 171 | 110 |
| 1800 | 143 | 20 | 194 | 124 |
| 2000 | 160 | 22 | 217 | 138 |
| 2200 | 176 | 24 | 239 | 152 |
| 2400 | 193 | 27 | 261 | 165 |
| 2600 | 209 | 29 | 284 | 179 |
| 2800 | 226 | 31 | 306 | 193 |
| 3000 | 242 | 33 | 328 | 207 |
| 3200 | 259 | 36 | 351 | 220 |
| 3400 | 275 | 38 | 373 | 234 |
| 3600 | 292 | 40 | 396 | 248 |
| 3800 | 308 | 43 | 418 | 262 |
| 4000 | 325 | 45 | 441 | 276 |
| 4200 | 342 | 47 | 463 | 290 |
| 4400 | 359 | 50 | 486 | 303 |
| 4600 | 375 | 52 | 509 | 317 |
| 4800 | 392 | 54 | 532 | 331 |
| 5000 | 409 | 57 | 554 | 345 |
| 5200 | 425 | 59 | 577 | 358 |
| 5400 | 442 | 61 | 599 | 372 |
| 5600 | 458 | 63 | 621 | 386 |
| 5800 | 475 | 66 | 643 | 400 |
| 6000 | 491 | 68 | 666 | 414 |
| 6200 | 508 | 70 | 688 | 427 |
| 6400 | 524 | 72 | 711 | 441 |
| 6600 | 541 | 75 | 733 | 455 |
| 6800 | 557 | 77 | 756 | 468 |
| 7000 | 574 | 79 | 778 | 482 |
| 7200 | 591 | 82 | 801 | 496 |
| 7400 | 608 | 84 | 824 | 510 |
| 7600 | 625 | 86 | 847 | 524 |
| 7800 | 642 | 89 | 870 | 538 |
| 8000 | 659 | 91 | 893 | 552 |
| 8200 | 675 | 93 | 915 | 565 |
| 8400 | 691 | 96 | 936 | 579 |
| 8600 | 706 | 98 | 958 | 593 |
| 8800 | 722 | 100 | 979 | 607 |
| 9000 | 738 | 102 | 1000 | 620 |
| 9200 | 755 | 104 | 1023 | 634 |
| 9400 | 772 | 107 | 1046 | 648 |
| 9600 | 788 | 109 | 1069 | 662 |
| 9800 | 805 | 111 | 1092 | 676 |
| 10000 | 822 | 114 | 1114 | 690 |